SC1/ 9580/24		FITNESS CERTIFICATE 2024 - 25 (Assistant Engineer/Assistant Executive Engineer)		
Name of School			APEX INTERNATIONAL SCHOOL	
1	N	lame of Officer	Ashwathy B	
2		ocation	Olavanna	
3		eriod for which the certificate is sued	2024-25	
4	Т	ypes of building	BLOCK 1 1) 6.00m x 6.00m x 3.60m - 11 Nos (GF) 2) 6.00m x 6.00m x 3.60m - 11 Nos (FF) 3) 6.00m x 6.00m x 3.60m - 11 Nos (SF) Total - 33 Nos	
5	N	ature of defect if any		
	a	Foundation and basement	Nil	
105-	b	Superstructure	Nil	
	C	Doors and windows	Nil	
	d	Wood work wrought up	Nil	
	e	Roof	Nil	
	f	flooring	Nil	
	g	miscellaneous (cracks if any)	No visible cracks found	
6	wi	ny major defects noticed which Il render the building unsafe in y manner	Nil	
7	WI bee	nether maintenance work have en done properly	Yes	
8	Wi	nether the structure is sound or t for conducting classes	Sound for conducting classes under normal wind and Weather condition	
ote	1	The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.		
	2	Any additional observation deemed necessary for the necessary for the certificate, may be furnished separately with the Certificate		
	Cer con	tified that the school was inspect duct classes for the period for the	ted by me on 25/10/2024 and found to be Fit to e stated above	

Place: Olavanna Date: 25/10/2024



Assistant Engineer ER